





SITE HEALTH & SAFETY INSPECTION

Site:	Hodgetts Estates Tamworth Core 42	By:	STEVE HARPER	Date:	Wednesday 6 th September 2017
OBSERVATIONS			CORRECTIVE ACTION		
1	<p>The welfare facilities continue to be kept in a high standard of cleanliness. All operatives are to be encouraged to maintain this standard.</p> <p>All mandatory notices are displayed and all relevant documentation is available and completed.</p>				<p>Well done good to see.</p>
	<p>Materials were being segregated into waste streams for removal off site. Asbestos cement from the roof sheets was segregated, stockpiled and being kept wet so as to prevent the potential of fibres being released into the air. This material was awaiting disposal to the appropriate waste facility.</p> 				<p>Excellent, well done.</p>
4	<p>Two way radio communications was being maintained between the site supervisor and the machine operator eliminating any requirement for personnel to be near the machine.</p>				<p>Good to see segregation of plant and personnel.</p>
5	<p>During the site tour operatives were engaged and questioned about their tasks and were able to demonstrate that they had been fully briefed on the method statement and gave clear explanations of their individual roles on site.</p>				<p>Excellent</p>
6	<p>PPE discipline on site overall is excellent, with operatives wearing the minimum mandatory site requirements.</p>				<p>Maintain standard.</p>



SITE HEALTH & SAFETY INSPECTION

7	<p>Slips, trips and falls are the biggest cause of accidents within the construction/demolition industry and accounts for a significant amount of lost time injuries being sustained.</p> <p>However the general site tidiness and housekeeping on this project site wide was very good.</p>	<p>Excellent. Supervisor is to ensure the current standard is maintained.</p>
Signed Inspector: 	Signed Site:	Distribution:
Notes:	Director:	PF & JS
	Client:	EH
	Senior Site Manager:	JR
	Inspection Number (on audit)	001/SH/17